

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

KR1455  
NNW  
> 1  
1.836 mi.  
9694 ft.

137 KINGS HWY  
137 KINGS HIGHWAY  
BROOKLYN, NY  
Site 1 of 3 in cluster KR

NY Spills S103275164  
N/A

Relative:  
Higher

Actual:  
19 ft.

SPILLS:

Name: 137 KINGS HWY  
Address: 137 KINGS HIGHWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9803303 / 1998-11-10  
Facility ID: 9803303  
Facility Type: ER  
DER Facility ID: 165923  
Site ID: 199354  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: B3  
SWIS: 2401  
Spill Date: 1998-06-15  
Investigator: MMMULQUE  
Referred To: Not reported  
Reported to Dept: 1998-06-15  
CID: 196  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Tank Tester  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: 1998-11-10  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1998-06-15  
Spill Record Last Update: 2004-03-09  
Spiller Name: PATRICA MCCARTIN  
Spiller Company: Not reported  
Spiller Address: 137 KINGS HWGY  
Spiller Company: 001  
Contact Name: PATRICA MCCARTIN  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
MULQUEEN NO PBS REGISTRATION SOIL MECHANICS DID TANK REMOVAL CLOSURE  
REPORT. MINIMAL RESIDUAL CONTAMINATION THAT REQUIRES NO FURTHER  
ACTIONS. "

Remarks: "WHILE REMOVING A TANK AT ABANDONED GAS STATION A SPILL WAS NOTICED  
UNKNOWN IF THIS HAS BEEN LEAKING OR THIS WAS DONE BY THE REMOVAL."

All Materials:

Site ID: 199354  
Operable Unit ID: 1064126  
Operable Unit: 01  
Material ID: 321618  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported